


Are these eggs? Or maybe tennis balls? "These things were hammering at our building."

The EIFS (Exterior Insulation and Finish System) is damaged.



The entire west side of the building is damaged including window coverings, furniture, carpet. Broken and splintered glass covers everything.



The EIFS, windows and shutters are left in shambles.



The residents felt like cannon were going off. It looked like a moat surrounded Crowell Home.



Is this snow? View from inside Crowell Home.

